# Streambank Damage Tour

August 30, 2023

## **Participants**

#### **Funding Entities:**

- DWR
- NDEP
- CTWCD
- CWSD

#### **Regulatory Agencies:**

- USACE
- NDEP

#### Other Participants:

- DCNR
- US Senator Rosen staff
- Conservation Districts
- CTWCD and CWSD Board Members







### Charney Site #4



10/13/21 Upstream looking down

11/22/22 Upstream looking down




04/27/23 Upstream looking down bank-full



7/28/23 Upstream looking down



#### **Running River Project**



June 2023 aerial imagery overlaid on ROA topo from July 2022

Running River - BEFORE AND AFTER UP STREAM LOOKING DOWN





Running River – August 2023



#### Two Ranch Road Project






7/2//23 Upstream looking down post-flooding

August 2023 looking upstream










#### **Riverbank Stabilization Project**

Carson River at Buzzy's Ranch Trail, Carson City, Nevada

Compiled by Carson City Parks, Recreation & Open Space
Department

Included: aerial imagery from 1994 – 2023 and photographs of the cutbank over the years from 2010 and 2023.












Photo 1: Taken February 25, 2010; looking northwest.



Photo 2: Taken November 2, 2010; looking north.



Photo 4: March 14, 2023; looking south.



Photo 9: May 22, 2023; water level high enough to kayak right up to cut bank.

